

LJ92-01511A
Power Supply PCB

Use in
Philips 50PFP5332D/37

Common problem is the caps. Change any that are puffed on the end.

DC8104

DC8105

DC8107

DC8413

DC8414

They are 680uf 50v.

DC8013 1000uf 16v

DC8419 3300uf 10v

If you find other parts bad on this item please post.